

BOX FLAT PACKING: Each garment flat packed (NO HALF-FOLDING) in a singled recycle OPP polybag with info sticker at bottom right corner. Please add 1 "Silicabag" inside each pocket.

Packed according to assortments mentioned in PO in a strong export carton with smallest sizes on top. Pls. use a piece of 3-ply carton in top & bottom of carton to secure garment, the carton has to be same size as the carton box. Every 2nd garment to be packed conversely.

Export cartons should be with logo, which fit the brand of the garments, shippingmarks PRINTED in black text at each long side and carton barcode sticker in each top right corner.

Please note below deviations:

Lindberg, Shine, Jack's, Morgan: Carton must be 7 ply in brown color, closed with 50 MM transparent tape. Follow cartons instructions in the supplier manual.

Bison and Junk de luxe: Carton must be 7 ply in colour white, be closed with 50 MM transparent tape. Follow cartons instructions in the supplier manual.

****ONLY CN orders are to be packed with two strong white plasticbands and Wagner logo tape. Please note that plasticbands are to be MELTED together. DK order should NOT have plastic bands**

Please visit our website www.pwtbrands.com and study all packing and shipment details!

